



Release Note

Software Version: 2.6.0.5850

Models: X1、X2、X2C、X3S、X4

Date: 2018-08-13



1 New Features

1. Added 'Enable Register MAC Header' in web configuration page, support the Mac field in the Register message.
2. Added Dutch.
3. Added Caller ID Type.
4. Added conference limitation function.

2 Optimization

1. Increase realm configuration maximum length to 64 bits
2. Optimized the incoming call interface in multiple call mode
3. Optimized the TR-069 function
4. Added the EHS Disable/Enable selection item on WEB/LCD
5. Support XXX format on dial plan
6. SIP display name support receive the escape character and restore the display
7. Fixed the related issues of BLF compatibility
8. Optimized the procession of BLF list
9. Support multiple languages on WEB error messages notice
10. Optimized the voice notice when the multicast listener get the multicast information
11. Optimized the cloud phonebook and URL function key by sending an HTTP request with the SIP(default) line without the username and password
12. Improve the software security.


3 BUG Fixes

1. Fixed the contact incomplete display issue in some LDAP servers
2. Fixed the main backup function of SIP Proxy
3. Fixed the issue that the LED light to be turned on or off not related to the configuration item
4. Fixed STUN stability issue.
5. Fixed the issue that the phone does not auto download the option 66 configuration file after getting VLAN ID
6. Fixed TLS calls can not resume hold issue on servers.
7. Fixed when the phone upgrade automatically, the interface showing problems.
8. Fixed the problem that the caller receives the 404 restart from the Avaya server.
9. Fixed the problem of automatically exiting to the standby screen after entering the screen saver for 2 minutes.
10. Fixed the issue that hold can not be resumed under certain servers when be called.
11. Fixed conference call can not be established in some cases.
12. Fixed the problem that 3CX uaCSTA is not connected properly after the phone is powered off.

4 New Features Description

1. Added 'Enable Register MAC Header' in web configuration page


Description: Add two configurations 'Enable Register MAC Header' and 'Enable MAC Header' on the web page. These two configuration items are primarily used to control whether sip registration package and the user agent include the MAC fields. The configuration on web page as follows:



2. Added Caller ID Type

Description: Phone caller IP type have three display options: Name priority, No display, Normal.

Normal mode is the color screen IP Phone default display mode. Name priority only shows the name. No display, the caller interface is blank, the name and number is not display. The configuration on web page as follows:



3. Added conference limitation function

Description: WEB add conference limit prefix and conference limit length

Parameter name	Description
Conference Limit Prefix	For example, if set to 0, the number starting with 0 cannot enter the conference.
Conference Limit Length	For example, if it is set to 4, the number above 4 cannot enter the me conference.

Web Page Configuration:

