

Fanvil

Version Number: 2.14.3

Applicable Model: H603W

Date: 2026.2.13

Content

1 Revision History	3
2 Release 2.14.3	4
2.1 New Features	4
2.2 New Feature Description	4
3 Release 2.14.0.11	6
3.1 Optimizations	6
3.2 Bug Fix	6
4 Release 2.14.0.8	7
4.1 New Features	7
4.2 Bug Fix	7

1 Revision History

No.	Version	Release Date
1	2.14.0.8	2024.11.18
2	2.14.0.11	2025.4.29
3	2.14.3	2026.2.13

2 Release 2.14.3

Model	Software Version	Remarks
H603W	2.14.3	

2.1 New Features

1. Add a new network configuration mode that supports connecting the device to the network via a mobile phone.
2. Add support for Wi-Fi security modes: 802.1X EAP-TLS and 802.1X EAP-TTLS.

2.2 New Feature Description


- 1. Add a new network configuration mode that supports connecting the device to the network via a mobile phone.**

Function Description: Switch the device to network configuration mode via a key combination, search for the device's Wi-Fi with a mobile phone, and connect the device to the network.


Setting Method:

- Press the key combination **#*123** on the device to enter network configuration mode. The SSID will be **<Device Model>_<Last 6 digits of MAC address>**, with no password; the indicator will flash red and green alternately.
- Use a mobile phone to search for and connect to this Wi-Fi (no password

required).The mobile phone will automatically redirect to the device network configuration page.



- On the page, select the security mode of the target Wi-Fi, enter the SSID and password, and submit. The H603W will automatically connect to the target network.



3 Release 2.14.0.11

Model	Software Version	Remarks
H603W	2.14.0.11	

3.1 Optimizations

1. Optimized the voice reminder for controller detachment timeout– press any button to interrupt the announcement

3.2 Bug Fix

1. Fixed audio stutter when pressing number keys in standby mode.

4 Release 2.14.0.8

Models	Software Version	Comment
H603W	2.14.0.8	

4.1 New Features

1. Add voice prompts for enabling and disabling mute.
2. Add a voice prompt feature when the handset exceeds the timeout for being off the base, reminding the user to return it to the base to avoid battery drain, enhancing the user experience.
3. Add automatic answering when the handset is lifted and automatic call hanging up when placed back on the base.

4.2 Bug Fix

1. Fix issues related to Wi-Fi auto deployment.